

Appendix C
June - September 2015
Fisheries Boardings with Violations

DATE	UNIT	VSL NAME	SPECIES	NOTES AND DETAILS
8/9/15	CHANDELEUR	AK2218AG	200	Insufficient fire extinguishers.
8/12/15	STA KETCHIKAN	WN7221SA	200	No visual distress signals, registration not onboard.
8/13/15	STA JUNEAU	HERON	430	Insufficient immersion suits and Type IV floatation device, fire extinguishers and sound producing device not onboard. Voyage termination.
8/23/15	STA KETCHIKAN	AK6798AM	200	Insufficient PFDs. Terminated voyage.
9/1/15	CHANDELEUR	TACOMA	NA	Insufficient Type IV floatation devices, EPIRB hydrostatic release incorrectly installed
9/5/15	ALEX HALEY	TAURUS	200	Expired hydrostatic release on EPIRB, expired visual distress signals
9/6/15	STA KETCHIKAN	AK9301F	200	No visual distress signals
9/7/15	STA KETCHIKAN	AK9359AL	200	Insufficient fire extinguisher and visual distress signals. Registration not onboard. Voyage terminated.
9/7/15	STA KETCHIKAN	WN5767NN	200	Type IV floatation device not onboard, insufficient fire extinguisher. Voyage terminated.
9/9/15	STA KETCHIKAN	AK1468AJ	200	Insufficient visual distress signals, registration not onboard
9/11/15	ALEX HALEY	SEA HAWK	200	Expired visual distress signals
9/11/15	ALEX HALEY	WHISTLER	200	No visual distress signals
9/11/15	ALEX HALEY	KACHEMAK KING	200	Insufficient amount of PFDs. Voyage terminated. Vessel was retaining mutilated halibut filets