17th Coast Guard District Report 2004 Year In Review



CDR Michael Cerne Operational Planning and Policy Division 9 February, 2005



Overview

- Resources
- Domestic Fisheries
- International Fisheries
- Safety
- Search & Rescue
- Maritime Security




Major Cutter & C-130 Effort

Major Cutter Days




Aircraft Hours






Patrol Boat Mission Emphasis





Fishing Vessel Boardings And Fisheries Violations

Vessels Boarded



Vessels With Violations





2004 Fishing Violations


At Sea

- -Lacey Act
- Transshipment
- -Closed Area
- Bycatch
- -Seabird Avoidance
- Permits
- Records/Reports
- Prohibited Species
- Highgrading
- -Shark Finning

Dockside

 Halibut Overage
 Logbook Violation





Critical Habitat Enforcement


Cutters: 3,679 Hours Aircraft: 565 Hours


Maritime Boundary Line Activity

Average Fleet Density 83 Incursions Detected 83 26 Vessels Identified 24 US Seizures ()**RS** Seizures 2 **Total Seizures** 2 Joint US/RS Boardings 1 Verbal Warnings Given 4 *Includes actual and suspected incursions ** Vessel later released due to technicality

1999 2000 2001 2002 2003 2004

50 <u>4</u>7 25 8 15 10 6 10 22 104 $\left(\right)$ $\left(\right)$ 6 $\left(\right)$ (), 6 9 13 10 6 6







International Fisheries


- USCG/Russia FSS Commanders Meeting
- Central Bering Sea Pollock Convention
- US-Russian Intergovernmental Consultative Committee on Fisheries
- North Pacific Heads of Coast Guard
- North Pacific Anadramous Fish Commission
- International Pacific Halibut Commission
- Dixon Entrance



At-Sea Fishing Vessel Boardings And Safety Violations



Vessels With Violations





2004 Fishing Vessel Safety Violations

(39)

(11)

(12)


(6)

(18)

(3) (4) (3)

(2)

-Insufficient/Expired Liferaft	(26)	 Missing/Expired Flares
 Insufficient Immersion Suits and Missing Lights 	(13)	 Insufficient/Unserviced Ring Buoy/PFD
-Insufficient Fire		– No Sound Producing Device
Extinguishers	(10)	 Missing Placards
– Expired EPIRB/Hydro	(15)	 No Documentation
- Expired Raft Hydro	(10)	– No MSD
 Insufficient Navigation Lights Unmaintained Equipment Security Zone Violation No Bilge Alarms 	(2) (2) (2) (2)	 Insufficient Hull Markings Insufficient Drills No Waste Plan



Fishing Vessel SAR Statistics

Deaths

Vessel Losses

CAUSE	FISHERY
Capsized1	Salmon1
Freon Leak1	Salmon1
Struck by Parted Line1	Pcod1
Man Overboard2	Salmon1
o " An	Halibut1
CAUSE	FISHERY
Capsized2	Salmon1
	Halibut1
Grounding5	Salmon5
Fire	Salmon1
Flooding1	Salmon1
	HER AMONG THE REPORT OF THE REPORT OF

2004 Crab Fisheries

2004 Opilio Fishery
 No SAR Cases

- No Lives or Vessels Losi

2004 Red King Crab Fishery
Four SAR Cases
Two Injuries (removed by helo)
No Lives or Vessels Lost



Selendang Ayu Update

Oil Lightered (CONFIRMED volume as of 03 FEB 05)

Oilec Solids Recovered (as of 02 FEB 05)

> Wilclife Impacts (as of 03 FEB 05)

Significant Events 03 FEB 05

Future Plans

•<u>MDO/Lube Oil (LIGHTERING COMPLETE)</u> •Approx 1173 gal skimmed from engine room •<u>Total</u> (all oil & engine room mix) 142,307 gal

23 cu yds since last report, Total to date: 616 cu yd (Material collected 03 & 04 Feb in transit to DH for measurement)

Dead Birds Recovered: 7 on Thursday, Total to date: 1536 Dead Mammals Recovered: No new findings, Total to date: 6

•ROV has been deployed to wreck site.

Aerial lightering as wx permits
Continue water & seafood sampling
Continue shoreline cleanup
State of Alaska requires salvage-bow section unlikely, stern section this summer



Maritime Homeland Security

- WPB/Small Boat Station in Valdez
- Anchorage MSST
- MTSA Security Plans
- 500 Vessel Escorts



