

SEVENTEENTH COAST GUARD DISTRICT




2002 Year-In-Review








Major Cutter & C-130 Effort





Fishing Vessel Boarding Statistics





2002 Fishing Violations

• At Sea

- US/RS MBL incursion (1)
- SSL Rookery Incursion(1)
- Outside Permit Area (3)
- High-grading Halibut (1)
- Permit Not On Board (4)
- -Bycatch Violation
- Seabird Avoidance (7)
- Logbook Violation





(3)

Dockside


- Cardholder Not Present (1)
- Retaining Sablefish
- Halibut Overage
- Failure to Sort Catch (2)
- Permit Not on Board (1)
- Mismarked Fish Totes (1)
- Logbook Violation




(1)

(4)

(7)








Maritime Boundary Line Activity

| DISTRIC | 1999 | 2000 | 2001 | 2002 | |
|----------------------------------------------------|------|------|-------|------|--|
| Incursions Detected* | 83 | 26 | 15 | 17 | |
| Vessels Identified | 24 | 22 | 10 | 14 | |
| US Seizures | 0 | 4 | 2 | 1** | |
| RS Seizures | 2 | 2 | 1 | 0 | |
| Total Seizures | 2 | 6 | 3 | 1 | |
| Joint US/RS Boardings | 1 | 4 | 1 | 0 | |
| Vessels Given Verbal Warnings | 4 | 9 | 6 | 13 | |
| *Includes actual and suspected incursions | | - 1 | Marti | | |
| **Vessel later released due to technicality | | XL. | | | |



MBL INCURSIONS 1997-2002





- Commander's Meetings Feb & Sep
- NPAFC Enforcement Meeting Kodiak
- Fisheries Enforcement Symposium P-K
- Adjudicator's Meeting Anchorage
- Sighting Reports & RS F/V arrivals
- Investigation Support






Future US-RS MBL Cooperation Plans

- Biannual Commander's Meeting
- Meeting of adjudicators
- Combined enforcement patrols
- Exchange of Officers
- Participation in US-RS ICC



US F/V Incursions into RS EEZ




TES



2002 HSDN Enforcement

- Feb Patrol Planning Meeting
- Canadian A/C patrol Apr/May
- USCG patrols before & after CA
- May ENFO Evaluation Meeting
- Oct NPAFC Annual Meeting







SUMMARY OF HSDN ACTIVITY

| Year | Detections | Seizures | Comments |
|--------------|------------|----------|--------------------------------------------------------------------------|
| 2002 2001 | 0 | 0 | There was no high seas driftnet activity detected. |
| 2000 | 2 | 1 | 1 HO targeting salmon. Seized by U.S. and auctioned for \$226,500. |
| 1999 | 10 | 3 | 2 RS and 1 PRC targeting salmon. PRC vsl seized by U.S. |
| 1998 | 9 | 3 | 2 PRC & 1 RS targeting salmon. Turned over to flag states |
| 1997 | 2 | 1 | Stateless vsl targeting tuna. Seized by U.S. |
| 1996 | 1 | 1 | Taiwan vsl targeting salmon Joint boarding, seized by Taiwan |



Fishing Vessel Boarding Safety Statistics





2002 Safety Violations


| – Master Intoxicated | (1) |
|----------------------|-----|
|----------------------|-----|


- Insufficient/Expired Liferaft (41)
- Insufficient Immersion Suits and Missing Lights (12)
- -Insufficient Fire
 - Extinguishers (14)
- Expired EPIRB (11)
- Failure to Conduct Drills (2)
- -Inoperative Alarm System
 - (Bilge and High Water) (2)
- Expired Hydrostatic Release (22)

| Exposed Hazards | (5) |
|--------------------------------------------------------------------|-------|
| Oil/Fuel Leaks | (3) |
| Missing/Expired Flares | (41) |
| Insufficient/Unserviced Ring Buoy/PFD | (21) |
| Failure to Monitor CH 16 | (1) |
| Operating Beyond License | (1) |
| No Sound Producing Device | (9) |
| Missing Placards | (5) |
| Insufficient Navigation Lights | (1) |
| Improperly Marked Equipmen | t (2) |



Safety Statistics





in the halibut or sablefish fisheries.

| VESSELS LOST FISHERY | | | | | | | |
|-------------------------|-----|------|-----|-------|-----|------|----|
| CAUSE | mon | Crap | Sab | Brish | Cod | Dive | |
| Fire | 5 | | | | 1 | | 6 |
| Grounding | 3 | 2 | | | | 1 | 6 |
| Flooding | 2 | 1 | 1 | 1 | | | 5 |
| Capsize | 1 | | 1 | | 1 | | 3 |
| Struck Log | 1 | | 1 | | | 1 | 3 |
| Mechanical | 2 | | | | | | 2 |
| Collision | 1 | | | | | | 1 |
| TOTAL | 15 | 3 | 3 | 1 | 2 | 2 | 26 |

| LIVES LOST FISHERY | | | | | | |
|-----------------------|---|---|---|---|----|--|
| CAUSE S THE SECOND | | | | | | |
| MOB* | 1 | 1 | 1 | 2 | 5 | |
| Fire** | | | | 3 | 3 | |
| Capsize | 1 | | | | 1 | |
| Fall | | 1 | | | 1 | |
| Crushed | 1 | | | | 1 | |
| TOTAL | 3 | 2 | 1 | 5 | 11 | |

*3 Pulled Overboard by Gear **All 3 from F/V Galaxy



Transition to the Department of Homeland Security

- USCG:
 - Lead for Maritime Homeland Security
 - Moves as intact, distinct entity
 - Maintains multi-mission focus
- Important relationship w/ Department of Transportation & others maintained
- Transition team is in place
- Transition plan due by 1 Mar

