

Appendix C

June – September 2020

Fisheries Boardings with Violations (Commercial, Recreational, and Charter)

DATE	VSL NAME	SPECIES	AREA	VIOLATIONS
6/1/20	MAVERICK	200	4B	Not retaining P-cod & Rockfish while fishing IFQ, not logging catch in required logbook, not recording discards
6/13/20	KENDRA H	410	508	Damaged/Degraded life ring
6/13/20	EYAK ONE	410	508	Inadequate number of fire extinguishers/Expired EPIRB hydrostatic release
6/15/20	5 STAR	420	508	Expired survival craft, expired survival craft equipment, expired EPIRB registration; Observed outside 3NM boundary line without CFVS decal; issued memo ordering inspection be completed within 30 days
6/17/20	NOMA	420	610	EXPIRED FLARE
6/17/20	CAROL ANN	420	610	EXPIRED LIFE RAFT
6/17/20	SVET	420	610	No child size immersion suit. Escorted to the pier
6/24/20	PACIFIC STAR	410	659	Master could not produce Certificate of Documentation
6/25/20	LITTLE TRACE	410	610	Violations issued for inadequate (expired) distress signals, markings on ring life buoy, and inadequate survival craft (service date). Corrected discrepancies. For ring life buoy tending line and mounting of hydrostatic release.
7/4/20	RAIDER	200	2C	No garbage placard, name/number not properly affixed
7/5/20	FIREFOX	410	659	Insufficient quantity of immersion suits and no inflatable buoyancy apparatus
7/8/20	ALASKAN HUNTER	200	2C	Failed to retain carcass of size restricted charter halibut
7/15/20	ALASKA OCEAN	270	524	Retention of Pacific Cod bycatch after 04MAY20,
7/18/20	SERENITY	200	2C	Joint-boarding with AST. Mutilated Halibut filleted and packaged onboard with no skin attached and multiple log book discrepancies. AST seized 31 halibut fillets
7/19/20	AK2526AK	200	2C	EXPIRED FLARES
7/22/20	ENDURANCE	200	3A	Improper marking on survival suit, expired EPIRB battery, unmarked EPIRB hydrostatic release expiration date
8/5/20	AK8281Ak	200	2C	No registration on board
8/8/20	CAROLYN ANN	200	2C	no survival craft
8/8/20	AK8579AJ	200	2C	incorrect fire extinguisher
8/14/20	TRITON	200	2C	Unserviceable ring buoy
8/15/20	NORTH STAR	430	650	EXPIRED DOCKSIDE EXAM
9/9/20	DEVOTION	200/710	AI	Not transmitting VMS while targeting Sablefish and 03 expired smoke floats
9/16/20	PEREGRINE	200/710	3A/WY	Expired flares
9/16/20	SISU	200/710	3A/WY	Expired Dockside exam sticker
9/17/20	JANI K	710/200	SE	No FCC SSL, No affixed official number, no crew member CPR certified, operating beyond 3NM without current dockside exam
9/19/20	MAGIA	710	SE	Not transmitting VMS while targeting Sablefish